



INSPECTION REPORT

TEXAS A & M UNIVERSITY
AT KINGSVILLE

Customer ID: 1497
Certificate: 74-R-0094

M S C 102, 700 UNIVERSITY BLVD
TEXAS A & M UNIVERSITY - KINGSVILLE
KINGSVILLE, TX 78363 8202

Site: 001
TEXAS A&M UNIVERSITY-

Inspection
Type: ROUTINE INSPECTION
Date: SEP-14-2004

**3.125
FACILITIES, GENERAL.**

(a) Structural strength. The facility must be constructed of such material and of such strength as appropriate for the animals involved. The indoor and outdoor housing facilities shall be structurally sound and shall be maintained in good repair to protect the animals from injury and to contain the animals.

NORTH DEER PENS : There are several areas where top support poles for the chain link fence have separated from the chain link fence . This allows the fence to sag . There was one pen gate which was bent and leaning . These areas pose potential injury areas for the 7 deer in these pens . The fence and gate needs to be repaired and maintained in good condition to protect and contain the animals . Correct By : 10-14-04

Prepared By: Elizabeth Pannill AM VMO
ELIZABETH PANNILL, V.M.O. , USDA, APHIS, Animal Care

Title: VETERINARY MEDICAL OFFICER , Inspector ID: 4018

Date:
SEP-14-2004

Received By: 7000 1520 0020 2997 263T
Certified Mail

Title:

*9648 per
green & white*

Date:
SEP-14-2004

*missing receipt that was
attached to this report.
MC 1/2/04*