U.S. DEPARTMENT OF AGRICULTURE
ANIMAL AND PLANT HEALTH INSPECTION SERVICE
WILDLIFE SERVICES

WILDLIFE SERVICES DEPREDATION INVESTIGATION REPORT

REPORT NUMBER: C 295

DATE COMPLAINT RECEIVED: 8-11-2010

SPECIES	NAME OF INVESTIGATOR(S)	DATE INVESTIGATED
wolf	Gary Looney	8-12-2010

NAME AND ADDRESS OF LIVESTOCK OWNER/LEASEE: (b)(3) (b)(6)

TELEPHONE NUMBER: (b)(3) (b)(6)

COUNTY: Nez Perce

LAND OWNERSHIP: ☐ STATE ☐ BLM ☐ TRIBAL ☒ PRIVATE ☐ FS ☐ OTHER (Specify)

TYPE OF LIVESTOCK/PROPERTY: ☐ HORSE ☐ BEES ☐ SHEEP ☒ CATTLE ☐ OTHER (Specify)

LOSSES AND/OR PROPERTY DAMAGE (See criteria on reverse side of form)

No. Confirmed	No. Probable	No. Possible/Unknown	No. Other (Specify)
1			

SITE DESCRIPTION/PHYSICAL EVIDENCE PRESENT (i.e., tracks, scat, hair, blood, signs of struggle, scrapes, etc.)

Tracks of several wolves. Signs of struggle (scrapes + tracks) at attack site. Kill site about 20' from Attack site. Large amount of Blood. Carcass moved about 15' from Kill site + fed upon. That's where it was found. moved another 30' + fed upon some more. N 46.75224 - W 116.37205

CARCASSES/PROPERTY DAMAGE CHARACTERISTICS (i.e., puncture marks, feeding patterns, measurements between canines, signs of hemorrhage, etc.)

Carcass was mostly consumed, however hind legs (lower) and one front leg were still available. Both hind legs and front legs showed considerable hemorrhage and bite marks. puncture marks seemed to be 1½ - 2¼".

ESTIMATED TIME SINCE PREDATION/DAMAGE OCCURRED (Days/hours): About 30 hrs or Less

ACTIONS TAKEN: Set 5 traps 8/12. T/K 2 wolves 8/13. T/K 1 wolf 8/17 T/K 1 wolf 8/20

DATE STARTED	DATE ENDED
8-12-210	8-20-10

ENTERED

NAME OF WS INVESTIGATOR	SIGNATURE	DATE
Gary Looney	Gary Looney	8-20-10
NAME OF DISTRICT SUPERVISOR	SIGNATURE	DATE
Todd Grimm	[illegible]	8/23/10
NAME OF STATE REPRESENTATIVE	SIGNATURE	DATE

DISPOSITION OF CARCASS/PARTS

WS FORM 200 (OCT 99) COPY DISTRIBUTION: WHITE - State Office YELLOW - District Supervisor PINK- State GOLDENROD- Investigator



U.S. DEPARTMENT OF AGRICULTURE
ANIMAL AND PLANT HEALTH INSPECTION SERVICE
WILDLIFE SERVICES

WILDLIFE SERVICES DEPREDATION INVESTIGATION REPORT

REPORT NUMBER: I 000336

DATE COMPLAINT RECEIVED: 8/14/2010

DATE INVESTIGATED: 8/16/2010

SPECIES: Wolf

NAME OF INVESTIGATOR(S): Doug Hansen

NAME AND ADDRESS OF LIVESTOCK OWNER/LEASEE: (b)(3) (b)(6) [redacted]

TELEPHONE NUMBER: (b)(3) (b)(6) [redacted]

COUNTY: Adams

LAND OWNERSHIP: [ ] STATE [ ] BLM [ ] TRIBAL [X] PRIVATE [ ] FS [ ] OTHER (Specify)

TYPE OF LIVESTOCK/PROPERTY: [ ] HORSE [ ] BEES [ ] SHEEP [X] CATTLE [ ] OTHER (Specify)

LOSSES AND/OR PROPERTY DAMAGE (See criteria on reverse side of form)

No. Confirmed	No. Probable	No. Possible/Unknown	No. Other (Specify)
2 Calves - Injured			

SITE DESCRIPTION/PHYSICAL EVIDENCE PRESENT (i.e., tracks, scat, hair, blood, signs of struggle, scrapes, etc.)

Wolf sign has been found in the area. There has been several confirmed wolf kills on this ranch this year already.

CARCASSES/PROPERTY DAMAGE CHARACTERISTICS (i.e., puncture marks, feeding patterns, measurements between canines, signs of hemorrhage, etc.)

Wolf canine stratches were found on the hind legs of both calves. One calf had more problems than the other. It had canine marks on the right front shoulder and infection and swelling in the left stifle joint and right hock.

ESTIMATED TIME SINCE PREDATION/DAMAGE OCCURRED (Days/hours): 2-3 Weeks

ACTIONS TAKEN

DATE STARTED	DATE ENDED

RECEIVED AUG 2 0 2010 WS

ENTERED

NAME	SIGNATURE	DATE
NAME OF WS INVESTIGATOR: Doug Hansen	Doug Hansen	8/19/2010
NAME OF DISTRICT SUPERVISOR: Todd Cain	[signature]	8/20/10
NAME OF STATE REPRESENTATIVE		

DISPOSITION OF CARCASS/PARTS

WS FORM 200 (OCT 99) COPY DISTRIBUTION: WHITE - State Office YELLOW - District Supervisor PINK- State GOLDENROD- Investigator











U.S. DEPARTMENT OF AGRICULTURE
ANIMAL AND PLANT HEALTH INSPECTION SERVICE
WILDLIFE SERVICES

WILDLIFE SERVICES DEPREDATION INVESTIGATION REPORT

REPORT NUMBER: JM 081210

DATE COMPLAINT RECEIVED: Aug 11 2010

SPECIES: Wolf

NAME OF INVESTIGATOR(S): Justin Mann

DATE INVESTIGATED: Aug 12, 2010

NAME AND ADDRESS OF LIVESTOCK OWNER: (b)(3) (b)(6) [redacted]

TELEPHONE NUMBER: (b)(3) (b)(6) [redacted]

COUNTY: Idaho

LAND OWNERSHIP: ☐ STATE ☐ BLM ☐ TRIBAL ☐ PRIVATE ☒ FS ☐ OTHER (Specify)

TYPE OF LIVESTOCK/PROPERTY: ☐ HORSE ☐ BEES ☐ SHEEP ☐ CATTLE ☐ OTHER (Specify)

LOSSES AND/OR PROPERTY DAMAGE (See criteria on reverse side of form)

No. Confirmed	No. Probable	No. Possible/Unknown	No. Other (Specify)
	1 Cow		

SITE DESCRIPTION/PHYSICAL EVIDENCE PRESENT (i.e., tracks, scat, hair, blood, signs of struggle, scrapes, etc.)

Wolf Track & Scat were All over The Area. One black wolf was Jumped off the Carcass as I Approached The Kill site. While I was Preforming The Necropsy 12-20 wolves were howling down wind within 200yds. wolf hair was found on The brush Around The Carcass. B274's signal was Really Close To The North of The Kill.

CARCASSES/PROPERTY DAMAGE CHARACTERISTICS (i.e., puncture marks, feeding patterns, measurements between canines, signs of hemorrhage, etc.)

The Carcass was mostly Consumed by wolves. It was eaten so Rapidly That Birds didn't have A Chance To Feed on it.

ESTIMATED TIME SINCE PREDATION/DAMAGE OCCURRED (Days/hours): ~ 3½ - 4 days

ACTIONS TAKEN

DATE STARTED	DATE ENDED

ENTERED

NAME OF WS INVESTIGATOR	SIGNATURE	DATE
Justin S. Mann	Justin S Mann	8/12/10
NAME OF DISTRICT SUPERVISOR	SIGNATURE	DATE
Todd Grimm	[illegible]	8/27/10
NAME OF STATE REPRESENTATIVE	SIGNATURE	DATE

DISPOSITION OF CARCASS/PARTS

WS FORM 200 (OCT 99) COPY DISTRIBUTION: WHITE - State Office YELLOW - District Supervisor PINK- State GOLDENROD- Investigator











U.S. DEPARTMENT OF AGRICULTURE
ANIMAL AND PLANT HEALTH INSPECTION SERVICE
WILDLIFE SERVICES

WILDLIFE SERVICES DEPREDATION INVESTIGATION REPORT

REPORT NUMBER: I 000341

DATE COMPLAINT RECEIVED: 8/24/2010

DATE INVESTIGATED: 8/24/2010

SPECIES: Wolf

NAME OF INVESTIGATOR(S): Doug Hansen

NAME AND ADDRESS OF LIVESTOCK OWNER/LEASEE: (b)(3) (b)(6) [redacted]

COUNTY: Idaho - (b)(3) (b)(6) [redacted]

LAND OWNERSHIP: ☐ STATE ☐ BLM ☐ TRIBAL ☐ PRIVATE ☒ FS ☐ OTHER (Specify)

TYPE OF LIVESTOCK/PROPERTY: ☐ HORSE ☐ BEES ☒ SHEEP ☐ CATTLE ☐ OTHER (Specify)

LOSSES AND/OR PROPERTY DAMAGE (See criteria on reverse side of form)

No. Confirmed	No. Probable	No. Possible/Unknown	No. Other (Specify)
1 Ewe, 2 Lambs			

SITE DESCRIPTION/PHYSICAL EVIDENCE PRESENT (i.e., tracks, scat, hair, blood, signs of struggle, scrapes, etc.)

Wolf scat and tracks were found in the area. Wolf scat was found near the lamb that was heavily fed upon.

CARCASSES/PROPERTY DAMAGE CHARACTERISTICS (i.e., puncture marks, feeding patterns, measurements between canines, signs of hemorrhage, etc.)

All three sheep had wolf canine puncture marks. The ewe had trauma to the neck and throat. One of the lambs had the trauma and hemorrhaging to the neck/throat area and also to the right hind leg. The second lamb was mostly consumed. The bone ends were chewed off and wolf canine puncture marks were found in the remaining hide.

ESTIMATED TIME SINCE PREDATION/DAMAGE OCCURRED (Days/hours): 24 Hrs.

ACTIONS TAKEN

DATE STARTED	DATE ENDED

ENTERED

NAME OF WS INVESTIGATOR: Doug Hansen	SIGNATURE: Doug Hansen	DATE: 8/26/2010
NAME OF DISTRICT SUPERVISOR: Todd Grimm	SIGNATURE: [signature]	DATE: 8/27/10
NAME OF STATE REPRESENTATIVE	SIGNATURE	DATE

DISPOSITION OF CARCASS/PARTS

WS FORM 200 (OCT 99) COPY DISTRIBUTION: WHITE - State Office YELLOW - District Supervisor PINK- State GOLDENROD- Investigator



Appendix A

U.S. DEPARTMENT OF AGRICULTURE
ANIMAL AND PLANT HEALTH INSPECTION SERVICE
WILDLIFE SERVICES

WILDLIFE SERVICES DEPREDATION INVESTIGATION REPORT

REPORT NUMBER: JM 83010

DATE COMPLAINT RECEIVED: Aug 30, 2010

SPECIES: Wolf

NAME OF INVESTIGATOR(S): Justin Mann

DATE INVESTIGATED: Aug 30, 2010

NAME AND ADDRESS OF LIVESTOCK OWNER/LESSEE: (b)(3) (b)(6)

TELEPHONE NUMBER: (b)(3) (b)(6)

COUNTY: Idaho

LAND OWNERSHIP: ☐ STATE ☐ BLM ☐ TRIBAL ☐ PRIVATE ☒ FS ☐ OTHER (Specify)

TYPE OF LIVESTOCK/PROPERTY: ☐ HORSE ☐ BEES ☐ SHEEP ☒ CATTLE ☐ OTHER (Specify)

LOSSES AND/OR PROPERTY DAMAGE (See criteria on reverse side of form)

No. Confirmed	No. Probable	No. Possible/Unknown	No. Other (Specify)
1 calf injured			

SITE DESCRIPTION/PHYSICAL EVIDENCE PRESENT (i.e., tracks, scat, hair, blood, signs of struggle, scrapes, etc.)

Calf was still alive & had been returned home. Attack site unknown

CARCASSES/PROPERTY DAMAGE CHARACTERISTICS (i.e., puncture marks, feeding patterns, measurements between canines, signs of hemorrhage, etc.)

2 1/4" canine spaced punctures and tears on both hind legs. A hunk of flesh the size of a tennis ball had been torn away from the left hind quarter. A piece of muscle & hide about the size of a softball had been torn from the belly/flank/front of right hind leg. Maggots in the wound indicated injury was days old

ESTIMATED TIME SINCE PREDATION/DAMAGE OCCURRED (Days/hours): ~ 4-6 days

ACTIONS TAKEN

8/30 Control action implemented

DATE STARTED	DATE ENDED
8/30	

NAME	SIGNATURE	DATE
NAME OF WS INVESTIGATOR: Justin Mann	Justin S. Mann	8/31/10
NAME OF DISTRICT SUPERVISOR: George Graves	[illegible]	7 Sept 2010
NAME OF STATE REPRESENTATIVE	SIGNATURE	DATE

DISPOSITION OF CARCASS/PARTS

WS FORM 200 (OCT 99) COPY DISTRIBUTION: WHITE - State Office YELLOW - District Supervisor PINK- State GOLDENROD- Investigator



USDA APHIS WILDLIF

U.S. DEPARTMENT OF AGRICULTURE
ANIMAL AND PLANT HEALTH INSPECTION SERVICE
WILDLIFE SERVICES

WILDLIFE SERVICES DEPREDATION INVESTIGATION REPORT

REPORT NUMBER: I 000340

SPECIES: Wolf	NAME OF INVESTIGATOR(S): Doug Hansen	DATE COMPLAINT RECEIVED: 8/22/10
		DATE INVESTIGATED: 8/23/10
NAME AND ADDRESS OF LIVESTOCK OWNER: (b)(3) (b)(6)		TELEPHONE NUMBER: (b)(3) (b)(6)
		COUNTY: Adams

LAND OWNERSHIP: ☐ STATE ☐ BLM ☐ TRIBAL ☐ PRIVATE ☒ FS ☐ OTHER (Specify)

TYPE OF LIVESTOCK/PROPERTY: ☐ HORSE ☐ BEES ☐ SHEEP ☒ CATTLE ☐ OTHER (Specify)

LOSSES AND/OR PROPERTY DAMAGE (See criteria on reverse side of form)

No. Confirmed	No. Probable	No. Possible/Unknown	No. Other (Specify)
1 Calf - Injured	1 Calf - Injured		

SITE DESCRIPTION/PHYSICAL EVIDENCE PRESENT (i.e., tracks, scat, hair, blood, signs of struggle, scrapes, etc.)

Multiple confirmed wolf damage from this area over the last several months.

CARCASSES/PROPERTY DAMAGE CHARACTERISTICS (i.e., puncture marks, feeding patterns, measurements between canines, signs of hemorrhage, etc.)

The confirmed calf had wolf canine scratches all over its right hind leg and a few on its left. The probable calf had scratches/cuts, but canine spacing could not be determined. The left hip had a lot of swelling and had to be lanced and drained. This calf had no use out of its left leg.

ESTIMATED TIME SINCE PREDATION/DAMAGE OCCURRED (Days/hours): 2-4 Weeks

ACTIONS TAKEN

DATE STARTED	DATE ENDED

ENTERED

NAME OF WS INVESTIGATOR: Doug Hansen	SIGNATURE: Doug Hansen	DATE: 8/24/10
NAME OF DISTRICT SUPERVISOR: Todd Grimm	SIGNATURE: [signature]	DATE: 8/25/10
NAME OF STATE REPRESENTATIVE	SIGNATURE	DATE

DISPOSITION OF CARCASS/PARTS

WS FORM 200 (OCT 99) COPY DISTRIBUTION: WHITE - State Office YELLOW - District Supervisor PINK- State GOLDENROD- Investigator









U.S. DEPARTMENT OF AGRICULTURE
ANIMAL AND PLANT HEALTH INSPECTION SERVICE
WILDLIFE SERVICES

WILDLIFE SERVICES DEPREDATION INVESTIGATION REPORT

REPORT NUMBER: I 000339

SPECIES: Wolf	NAME OF INVESTIGATOR(S): Doug Hansen	DATE COMPLAINT RECEIVED: 8/19/2010
		DATE INVESTIGATED: 8/20/2010
NAME AND ADDRESS OF LIVESTOCK OWNER/LEASEE: (b)(3) (b)(6)		TELEPHONE: (b)(3) (b)(6)
		COUNTY: Adams

LAND OWNERSHIP: ☐ STATE ☐ BLM ☐ TRIBAL ☐ PRIVATE ☒ FS ☐ OTHER (Specify)

TYPE OF LIVESTOCK/PROPERTY: ☐ HORSE ☐ BEES ☐ SHEEP ☒ CATTLE ☐ OTHER (Specify)

LOSSES AND/OR PROPERTY DAMAGE (See criteria on reverse side of form)

No. Confirmed	No. Probable	No. Possible/Unknown	No. Other (Specify)
	1 Cow		

SITE DESCRIPTION/PHYSICAL EVIDENCE PRESENT (i.e., tracks, scat, hair, blood, signs of struggle, scrapes, etc.)

Wolf tracks and scat in the area. Producers and USDA Wildlife Services have had confirmed wolf sightings. Confirmed wolf depredation on 8/13/2010.

CARCASSES/PROPERTY DAMAGE CHARACTERISTICS (i.e., puncture marks, feeding patterns, measurements between canines, signs of hemorrhage, etc.)

Wolf canine scratches were found on the cow's nose, chest, side, flank, and hind leg. The bag and intestines were the only parts eaten. The cow had been dead long enough that the hide was drying out and getting hard.

ESTIMATED TIME SINCE PREDATION/DAMAGE OCCURRED (Days/hours): 3-4 weeks

ACTIONS TAKEN

DATE STARTED	DATE ENDED

ENTERED

NAME OF WS INVESTIGATOR: Doug Hansen	SIGNATURE: Doug Hansen	DATE: 8/23/2010
NAME OF DISTRICT SUPERVISOR: Todd Grimm	SIGNATURE: [signature]	DATE: 8/25/10
NAME OF STATE REPRESENTATIVE	SIGNATURE	DATE

DISPOSITION OF CARCASS/PARTS











U.S. DEPARTMENT OF AGRICULTURE
ANIMAL AND PLANT HEALTH INSPECTION SERVICE
WILDLIFE SERVICES

WILDLIFE SERVICES DEPREDATION INVESTIGATION REPORT

REPORT NUMBER: I 000338

DATE COMPLAINT RECEIVED: 8/19/2010

DATE INVESTIGATED: 8/19/2010

SPECIES: Wolf

NAME OF INVESTIGATOR(S): Doug Hansen

NAME AND ADDRESS OF LIVESTOCK OWNER/LEASEE: (b)(6),(b)(3) Soulen Livestock, P.O. Box 827, Weiser, Idaho 83672

TELEPHONE NUMBER: (b)(6),(b)(3) 208-549-1878

COUNTY: Valley - Fisher Creek

LAND OWNERSHIP: [ ] STATE [ ] BLM [ ] TRIBAL [ ] PRIVATE [X] FS [ ] OTHER (Specify)

TYPE OF LIVESTOCK/PROPERTY: [ ] HORSE [ ] BEES [X] SHEEP [ ] CATTLE [ ] OTHER (Specify)

LOSSES AND/OR PROPERTY DAMAGE (See criteria on reverse side of form)

No. Confirmed	No. Probable	No. Possible/Unknown	No. Other (Specify)
1 Ewe			

SITE DESCRIPTION/PHYSICAL EVIDENCE PRESENT (i.e., tracks, scat, hair, blood, signs of struggle, scrapes, etc.)

Wolf tracks at the attack site. The herder has been hearing multiple wolves howling almost every night. On 8/15/2010 a lamb was confirmed killed by wolves.

CARCASSES/PROPERTY DAMAGE CHARACTERISTICS (i.e., puncture marks, feeding patterns, measurements between canines, signs of hemorrhage, etc.)

Wolf canine puncture marks were found around the ewe's neck. Deep hemorrhaging occurred in the tissue at these marks. No feeding had been found on the ewe.

ESTIMATED TIME SINCE PREDATION/DAMAGE OCCURRED (Days/hours): 8-10 Hours

ACTIONS TAKEN

DATE STARTED	DATE ENDED

NAME OF WS INVESTIGATOR: Doug Hansen	SIGNATURE: Doug Hansen	DATE: 8/23/2010
NAME OF DISTRICT SUPERVISOR: Todd Coleman	SIGNATURE: [signature]	DATE: 8/25/10
NAME OF STATE REPRESENTATIVE	SIGNATURE	DATE

DISPOSITION OF CARCASS/PARTS

WS FORM 200 (OCT 99) COPY DISTRIBUTION: WHITE - State Office YELLOW - District Supervisor PINK- State GOLDENROD- Investigator

U.S. DEPARTMENT OF AGRICULTURE
ANIMAL AND PLANT HEALTH INSPECTION SERVICE
WILDLIFE SERVICES

WILDLIFE SERVICES DEPREDATION INVESTIGATION REPORT

REPORT NUMBER: I 000342

DATE COMPLAINT RECEIVED: 8/13/2010

DATE INVESTIGATED: 8/13/2010

SPECIES: Wolf

NAME OF INVESTIGATOR(S): Doug Hansen

NAME AND ADDRESS OF LIVESTOCK OW (b)(3) (b)(6)

TELEPHONE NUMBER: (b)(3) (b)(6)

COUNTY: Adams

LAND OWNERSHIP: ☐ STATE ☐ BLM ☐ TRIBAL ☐ PRIVATE ☒ FS ☐ OTHER (Specify)

TYPE OF LIVESTOCK/PROPERTY: ☐ HORSE ☐ BEES ☐ SHEEP ☒ CATTLE ☐ OTHER (Specify)

LOSSES AND/OR PROPERTY DAMAGE (See criteria on reverse side of form)

No. Confirmed	No. Probable	No. Possible/Unknown	No. Other (Specify)
1 Bull			

SITE DESCRIPTION/PHYSICAL EVIDENCE PRESENT (i.e., tracks, scat, hair, blood, signs of struggle, scrapes, etc.)

Wolf tracks were found in the area and around the carcass. The produce had seen a wolf the day before the investigation in the area of the bull carcass. Historical wolf problem area.

CARCASSES/PROPERTY DAMAGE CHARACTERISTICS (i.e., puncture marks, feeding patterns, measurements between canines, signs of hemorrhage, etc.)

Wolf canine puncture marks were found in the head, neck, front legs, hind legs, scrotum, and back. Due to the advanced stages of decay signs of hemorrhage were difficult to find, but enough was found for conformation.

ESTIMATED TIME SINCE PREDATION/DAMAGE OCCURRED (Days/hours): 10-12 Days

ACTIONS TAKEN

DATE STARTED	DATE ENDED

ENTERED

RECEIVED AUG 2 0 2010 WS

NAME	SIGNATURE	DATE
NAME OF WS INVESTIGATOR: Doug Hansen	Doug Hansen	8/16/2010
NAME OF DISTRICT SUPERVISOR: Todd Grimm	[illegible]	8/20/10
NAME OF STATE REPRESENTATIVE		

DISPOSITION OF CARCASS/PARTS

WS FORM 200 (OCT 99) COPY DISTRIBUTION: WHITE - State Office YELLOW - District Supervisor PINK- State GOLDENROD- Investigator











U.S. DEPARTMENT OF AGRICULTURE
ANIMAL AND PLANT HEALTH INSPECTION SERVICE
WILDLIFE SERVICES

WILDLIFE SERVICES DEPREDATION INVESTIGATION REPORT

REPORT NUMBER: I 000334

DATE COMPLAINT RECEIVED: 8/11/2010

DATE INVESTIGATED: 8/12/2010

SPECIES: Wolf

NAME OF INVESTIGATOR(S): Doug Hansen

NAME AND ADDRESS OF LIVESTOCK OWNER/LEASEE: (b)(3) (b)(6) [redacted]

TELEPHONE NUMBER: (b)(3) (b)(6) [redacted]

COUNTY: Valley - Josephine

LAND OWNERSHIP: ☐ STATE ☐ BLM ☐ TRIBAL ☐ PRIVATE ☒ FS ☐ OTHER (Specify)

TYPE OF LIVESTOCK/PROPERTY: ☐ HORSE ☐ BEES ☒ SHEEP ☐ CATTLE ☐ OTHER (Specify)

LOSSES AND/OR PROPERTY DAMAGE (See criteria on reverse side of form)

No. Confirmed	No. Probable	No. Possible/Unknown	No. Other (Specify)
1 Ewe	1 Lamb		

SITE DESCRIPTION/PHYSICAL EVIDENCE PRESENT (i.e., tracks, scat, hair, blood, signs of struggle, scrapes, etc.)

Wolf tracks were found in the area. Historical wolf problem area.

CARCASSES/PROPERTY DAMAGE CHARACTERISTICS (i.e., puncture marks, feeding patterns, measurements between canines, signs of hemorrhage, etc.)

The ewe had wolf canine puncture marks on the inside and outside of her right hind leg. Due to the injuries the ewe could barely walk and infection was setting in. This ewe will die within days. The lamb was mostly consumed. Large canine holes were found in some of the pieces of hide. Canine spacing could not be determined.

ESTIMATED TIME SINCE PREDATION/DAMAGE OCCURRED (Days/hours): 1-2 Days

ACTIONS TAKEN

DATE STARTED	DATE ENDED

RECEIVED AUG 20 2010 WS

ENTERED

NAME OF WS INVESTIGATOR: Doug Hansen	SIGNATURE: Doug Hansen	DATE: 8/16/2010
NAME OF DISTRICT SUPERVISOR: TODD GRIMM	SIGNATURE: [signature]	DATE: 8/20/10
NAME OF STATE REPRESENTATIVE	SIGNATURE	DATE

DISPOSITION OF CARCASS/PARTS

WS FORM 200 (OCT 99) COPY DISTRIBUTION: WHITE - State Office YELLOW - District Supervisor PINK- State GOLDENROD- Investigator

U.S. DEPARTMENT OF AGRICULTURE
ANIMAL AND PLANT HEALTH INSPECTION SERVICE
WILDLIFE SERVICES

WILDLIFE SERVICES DEPREDATION INVESTIGATION REPORT

REPORT NUMBER: I 000335

DATE COMPLAINT RECEIVED: 8/14/2010

DATE INVESTIGATED: 8/15/2010

SPECIES: Wolf

NAME OF INVESTIGATOR(S): Doug Hansen

NAME AND ADDRESS OF LIVESTOCK OWNER/LE[redacted] (b)(3) (b)(6)

TELEPHONE NUMBER: [redacted] (b)(3) (b)(6)

COUNTY: Valley - Fisher Cr.

LAND OWNERSHIP: ☐ STATE ☐ BLM ☐ TRIBAL ☐ PRIVATE ☒ FS ☐ OTHER (Specify)

TYPE OF LIVESTOCK/PROPERTY: ☒ SHEEP ☐ CATTLE ☐ OTHER (Specify) ☐ HORSE ☐ BEES

LOSSES AND/OR PROPERTY DAMAGE (See criteria on reverse side of form)

No. Confirmed	No. Probable	No. Possible/Unknown	No. Other (Specify)
1 Lamb			

SITE DESCRIPTION/PHYSICAL EVIDENCE PRESENT (i.e., tracks, scat, hair, blood, signs of struggle, scrapes, etc.)

Herders heard five wolves howling. Wolf tracks were observed at the attack site.

CARCASSES/PROPERTY DAMAGE CHARACTERISTICS (i.e., puncture marks, feeding patterns, measurements between canines, signs of hemorrhage, etc.)

Hemorrhaging and wolf canine puncture marks were found on the neck and right hind leg.

ESTIMATED TIME SINCE PREDATION/DAMAGE OCCURRED (Days/hours): 24 Hrs.

ACTIONS TAKEN

DATE STARTED	DATE ENDED

RECEIVED AUG 20 2010 WS

ENTERED

NAME OF WS INVESTIGATOR: Doug Hansen	SIGNATURE: Doug Hansen	DATE: 8/16/2010
NAME OF DISTRICT SUPERVISOR: Todd Grimm	SIGNATURE: [signature]	DATE: 8/20/10
NAME OF STATE REPRESENTATIVE	SIGNATURE	DATE

DISPOSITION OF CARCASS/PARTS

WS FORM 200 (OCT 99) COPY DISTRIBUTION: WHITE - State Office YELLOW - District Supervisor PINK- State GOLDENROD- Investigator