



3482 cust\_id  
258137 insp\_id  
3345 site\_id

**INSPECTION REPORT**

**CHEYENNE MTN ZOOL. SOCIETY  
CHEYENNE MOUNTAIN ZOO. PARK**

**Customer ID: 3482  
Certificate: 84-C-0001**

**4250 CHEYENNE MTN. ZOO RD.  
COLORADO SPGS, CO 80906**

**Site: 001  
CHEYENNE MOUNTAIN ZOO. PARK**

**Inspection  
Type: ROUTINE INSPECTION  
Date: JUN-13-2005**

**3.127 ( d )  
FACILITIES, OUTDOOR.**

3.127(d) Facilities Outdoor. Perimeter. Facilities not entirely indoors must be enclosed by a perimeter fence that is of sufficient height to keep animals and unauthorized persons out. Fence less than 8 feet high for potentially dangerous animals. The fence must be constructed so that it protects the animals in the facility by restricting animals and unauthorized persons from going through it or under it and having contact with the animals in the facility, and so that it can function as a secondary containment system for the animals.

A survey of the perimeter fence surrounding the zoo grounds revealed approximately 25 acres where there is sufficient space at the bottom of the fence to allow animals from the outside to enter the zoo grounds. Mid way down the north side is about 50-60 feet of fencing that is not attached at the top leaving large openings for animals to enter the grounds. The north side towards the top of the hill has 2 support poles with large amounts of pits, cracks, and rust causing the poles to lose it strength in supporting the fencing. Along the northeast side near the utility access road about 40-50 feet of fencing is only about 6 feet high.

Fencing must be constructed and kept in good repair, so that it protects the animals in the facility.  
To be corrected by: August 13, 2005

Inspection accompanied by (b)(6), (b)(7)(c)

Inspection was limited to PPEQ Inspection, African Rift, Elephant Barn, Commissary and Pony Ride.

Prepared (b)(6), (b)(7)(c)  
T  
Received  
T

**Date:**  
JUN-13-2005

**Date:**  
JUN-13-2005

JUN 21 2005